

SHIPS CLASSIFICATION MALAYSIA

CERTIFICATE OF APPROVAL FOR SERVICE FIRMS/STATIONS/SUPPLIERS

Certificate No: SCM-FFE-22-14

Captain M. Prathaban

General Manager

Name of Service Firms:

PT. BATAM MARINE INDOBAHARI

Business Address

Kompleks Pusat Seken, Bukit Beruntung Blok B VIII No 25-26 Sei Panas Batam, Province Kepulauan Riau,

Indonesia.

This is to certify that the above-named company has been approved for carrying out class and statutory service in the following work area:

SURVEY AND MAINTENANCE OF FIRE EXTINGUISHING **EQUIPMENTS, SYSTEMS AND SELF CONTAINED BREATHING APPARATUS**

ON

THE SCM'S CLASSED SHIPS

Upon satisfactory verification of the company's procedures in accordance to SCM VENDOR SELECTION PROCEDURE for Approval of Service Firms/Stations/Suppliers Rev. 1

> Date of Verification 15 September 2022 Place of Verification Batam, Indonesia. Issue Date 30 September 2022 Place of Issue Shah Alam, Selangor.

This certificate is valid until 15 September 2025

Wohel Syamsul Bahtiar Surveyor

This certificate is subject to cancellation if The service is not properly carried out

The results are improperly reported SCM Surveyors/Auditors found deficiencies in the approval cry e operation and appropriate action is not taken Fails to inform of any alterations

Additional audit if requested has not been carried out

Willful acts or omissions are ascertained

License revoked by the Flag Administration (where applicable)

FORM NO .: TE/CESA/F/1



SHIPS CLASSIFICATION MALAYSIA

CERTIFICATE OF APPROVAL FOR SERVICE FIRMS/STATIONS/SUPPLIERS

Certificate No: SCM-LBT-22-15

Captain M. Prathaban General Manager

Name of Service Firms: PT. BATAM MARINE INDOBAHARI

Business Address Kompleks Pusat Seken, Bukit Beruntung Blok B VIII

No 25-26 Sei Panas Batam, Province Kepulauan Riau,

Indonesia.

This is to certify that the above-named company has been approved for carrying out class and statutory service in the following work area:

SERVICING AND MAINTENANCE OF LIFEBOAT, LAUNCHING APPLIANCES, ON-LOAD RELEASE GEARS AND DAVIT-LAUNCHED LIFERAFT RELEASE HOOKS

ON

THE SCM'S CLASSED SHIPS

Upon satisfactory verification of the company's procedures in accordance to SCM VENDOR SELECTION PROCEDURE for Approval of Service Firms/Stations/Suppliers Rev. 1

> Date of Verification 15 September 2022 Place of Verification Batam, Indonesia. Issue Date 30 September 2022 Place of Issue Shah Alam, Selangor.

This certificate is valid until 15 September 2025

Mohd Syamsul Bahtiar Surveyor

This certificate is subject to cancellation if: The service is not properly carried out

The results are improperly reported SCM Surveyors/Auditors found deficiencies in the approvalment de operation and appropriate action is not taken

Fails to inform of any alterations Additional audit if requested has not been carried out

Willful acts or omissions are ascertained

License revoked by the Flag Administration (where applicable)

FORM NO .: TE/CESA/F/1



SHIPS CLASSIFICATION MALAYSIA

CERTIFICATE OF APPROVAL FOR SERVICE FIRMS/STATIONS/SUPPLIERS

SCM

Certificate No: SCM-LRT-22-16

Captain M. Prathaban

General Manager

Name of Service Firms:

PT. BATAM MARINE INDOBAHARI

Business Address

Kompleks Pusat Seken, Bukit Beruntung Blok B VIII

No 25-26 Sei Panas Batam, Province Kepulauan Riau,

Indonesia.

This is to certify that the above-named company has been approved for carrying out class and statutory service in the following work area:

INFLATABLE LIFERAFTS, INFLATABLE LIFEJACKETS, HYDROSTATIC RELEASE UNITS, INFLATABLE RESCUE BOATS AND MARINE EVACUATION SYSTEMS

ON

THE SCM'S CLASSED SHIPS

Upon satisfactory verification of the company's procedures in accordance to SCM VENDOR SELECTION PROCEDURE for Approval of Service Firms/Stations/Suppliers Rev. 1

Date of Verification : 15 September 2022
Place of Verification : Batam, Indonesia.
Issue Date : 30 September 2022
Place of Issue : Shah Alam, Selangor.

This certificate is valid until 15 September 2025

Mohd Syamsul Bahtiar Surveyor

This certificate is subject to cancellation if: The service is not properly carried out The results are improperly reported

SCM Surveyors/Auditors found deficiencies in the approval sevils operation and appropriate action is not taken

Fails to inform of any alterations

Additional audit if requested has not been carried out

Willful acts or omissions are ascertained

License revoked by the Flag Administration (where applicable)